



Not sure if your unit requires an upgrade to remain compliant with current guidelines?
Follow the chart below to determine the best path to upgrade your equipment.

Canadian EMV and Interac/PCI Upgrade Path for Triton XScale/X2 ATMs

RL1600, RL2000, RL5000, RT2000, FT5000

