

GURUS FLAT RATE REPAIR SCHEDULE

Date: May 2010

ATMGurus provides a comprehensive repair program for most common components in all entry-level ATM brands. All repairs come with our Guru Guarantee*.



A complete listing is provided. Items are periodically updated to reflect additions of new items and removal of some older items. We will make every effort to provide convenient repair options for you. In addition, some items are offered under our multi-level repair program. You will see both STANDARD and DELUXE offerings on select repair items. This program is designed to address basic repairs and full rebuilds, depending on your needs and budget.

You can contact a Customer Service Guru by e-mail at customer.service@atmgurus.com or by telephone at +1-901-728-6487 or 1-888-7-ATMGurus (1-888-728-6487) toll free in North America and they will generate a sales order for your repair, or visit our online RMA tool and open your own RMA improving your repair turn-around times.

A return material authorization (RMA) will be provided to you, and that is your tracking identification within ATMGurus. You must mark the package with the RMA number, and return to our Memphis facility.

Part #	Make	Type	Description	Price
01162-00005 08010-06011	Triton	Card Readers	Triton 8100/9100/9600/9700/MAKO Trk 1-2 Mag-Stripe Card Reader Repair	\$ 50.00
01162-00008 08010-00128	Triton	Card Readers	Triton FT5000/RL1600/RL2000/RL5000/RL5000XP/RT2000 Trk 1-2 Mag-Stripe Card Reader Repair	\$ 50.00
01162-00009 08010-00129	Triton	Card Readers	Triton 9700 Trk 2-3 Mag-Stripe Card Reader Repair	\$ 50.00
01162-00016 08010-02016	Triton	Card Readers	Triton 9100/9600/9700/FT5000/RL2000/RL5000/RL5000XP/RT2000 EMV I-65 Card Reader Repair	\$ 150.00
06200-00087 08011-00006	Triton	Mainboards & Electronics	Triton FT5000/RL5000 Xscale Docking Board Repair	\$ 50.00
06200-00159 08011-00007	Triton	Mainboards & Electronics	Triton RT2000 Xscale Docking Board Repair	\$ 50.00
09200-00066 08010-00116	Triton	Mainboards & Electronics	Triton FT5000/RL5000/RT2000 X-Scale Mainboard Software Load/Recovery & Component Repair	\$ 300.00
06200-08146 08011-08146	Triton	Mainboards & Electronics	Triton FT5000/RL5000/RL2000/RT2000 X2 Mainboard Software Load/Recovery & Component Repair	\$ 250.00
06100-08133 08011-08133	Triton	Mainboards & Electronics	Triton RL1600 X2 Mainboard Software Load/Recovery & Component Repair	\$ 250.00
09200-00075 08010-00026	Triton	Mainboards & Electronics	Triton 9100/9600/MAKO/9700/FT5000/RL5000 Electronic Journal Repair	\$ 50.00
06200-00008 08010-00080	Triton	Mainboards & Electronics	Triton 9100 Monochrome Mainboard Standard Repair (Includes testing and reload of software only)	\$ 95.00
06200-00008 08010-00080	Triton	Mainboards & Electronics	Triton 9100 Monochrome Mainboard Software Load/Recovery & Component Repair	\$ 200.00
06200-00012 08010-11209	Triton	Mainboards & Electronics	Triton 9100 Color Mainboard Standard Repair (Includes testing and reload of software only)	\$ 95.00

06200-00012 08010-11209	Triton	Mainboards & Electronics	Triton 9100 Color Mainboard Software Load/Recovery & Component Repair	\$ 200.00
09600-02004 08010-06009	Triton	Mainboards & Electronics	Triton 9600 SS3 1 Meg Memory Expansion Board Repair	\$ 85.00
09600-02001 08010-06006	Triton	Mainboards & Electronics	Triton 9600 SS1 CPU Module Repair	\$ 75.00
09600-01024 08010-06003	Triton	Mainboards & Electronics	Triton 9600 Backplane Board Repair	\$ 75.00
09600-02086 08010-00057	Triton	Mainboards & Electronics	Triton 9600 SS2 Memory Module Repair	\$ 100.00
09600-02076 08010-06028	Triton	Mainboards & Electronics	Triton 9600 Modem Repair	\$ 125.00
09100-00119 08010-00070	Triton	Mainboards & Electronics	Triton 9700 Docking Board Repair	\$ 25.00
06200-00062 08010-00066	Triton	Mainboards & Electronics	Triton 9700 Mainboard Standard Repair (Includes testing and reload of software only)	\$ 95.00
06200-00062 08010-00066	Triton	Mainboards & Electronics	Triton 9700 Mainboard Software Load/Recovery & Component Repair	\$ 200.00
09110-00149 08010-00173	Triton	Mainboards & Electronics	Triton 8100 Mainboard Software Load/Recovery & Component Repair	\$ 200.00
09105-00291 08010-11312	Triton	Mainboards & Electronics	Triton FT7000 UCV Board Repair	\$ 200.00
09105-00289 08010-11294	Triton	Mainboards & Electronics	Triton FT7000 Docking Board Repair	\$ 250.00
09006-00015	Triton	Mainboards & Electronics	Triton FT7000 Envelope Depository Unit Repair	\$ 500.00
06100-00710 08010-11314	Triton	Mainboards & Electronics	Triton FT7000 PC w/Prism Repair	\$ 700.00
06100-00605 08010-11111	Triton	Mainboards & Electronics	Triton FT5000XP/RL5000XP PC w/Prism Repair	\$ 700.00
01500-00005 08010-00152	Triton	Printers	Triton FT5000/RL5000/RL2000/RT2000 X2 80mm Printer Cutter Repair	\$ 50.00
01500-00119	Triton	Printers	Triton FT5000/FT5000XP/RL5000/RL5000XP/RT2000 Xscale Printer Controller Board Repair	\$ 85.00
01260-00023 08010-11330	Triton	Printers	Triton FT5000/RL5000/RL2000/RT2000/RL1600 X2 Printer Controller Board Repair	\$ 85.00
09200-00060 08010-00168	Triton	Printers	Triton FT5000/FT5000XP/RL5000/RL5000XP/RT2000 Xscale Printer Presenter Repair	\$ 60.00
09200-00114 08010-00178	Triton	Printers	Triton FT5000/RL5000/RT2000 X2 Printer Presenter Repair	\$ 60.00
09200-00071 08010-00169	Triton	Printers	Triton RL5000 Xscale 80mm Printer Assembly Repair	\$ 275.00
09200-00062 08010-00170	Triton	Printers	Triton FT5000 Xscale 80mm Printer Assembly Repair	\$ 275.00
09200-00070 08010-00214	Triton	Printers	Triton RT2000 Xscale 80mm Printer Assembly Repair	\$ 275.00
09200-00139 08010-11119	Triton	Printers	Triton RT2000 X2 80mm Printer Assembly Repair	\$ 225.00
09200-00112 08010-01120	Triton	Printers	Triton RL5000 X2 80mm Printer Assembly Repair	\$ 225.00
09200-00130 08010-11130	Triton	Printers	Triton FT5000 X2 80mm Printer Assembly Repair	\$ 225.00
09110-00072 08010-00772	Triton	Printers	Triton RL1600/RL2000 60mm Printer Assembly Repair	\$ 200.00

09110-00075	08010-00775	Triton	Printers	Triton RL2000 80mm Printer Assembly Repair	\$ 200.00
09800-00103	08010-00223	Triton	Printers	Triton 9100/9600/9700/MAKO/RL2000 60mm Printer Cutter Repair	\$ 50.00
06200-00114	08011-00153	Triton	Printers	Triton 9100/MAKO Printer Controller Board Repair	\$ 85.00
09110-00159	08010-11274	Triton	Printers	Triton 9100 60mm Printer Assembly Repair	\$ 100.00
09600-02008	08010-06004	Triton	Printers	Triton 9600 Printer Assembly w/Controller Repair	\$ 225.00
06200-08182	08011-00153	Triton	Printers	Triton 9700 Printer Controller Board Repair	\$ 85.00
01500-00105	08010-22105	Triton	Printers	Triton 8100 58mm Printer Cutter Repair	\$ 50.00
09110-00008	08010-00167	Triton	Printers	Triton 8100 58mm Printer Assembly Repair	\$ 100.00
01500-00111	08010-50111	Triton	Printers	Triton FT7000 80mm Thermal Printer Module Repair	\$ 425.00
09200-00107	08010-01107	Triton	Power Supplies	Triton FT5000/RL5000 Single Power Supply Sub-Assembly Repair	\$ 150.00
09200-00109	08010-01515	Triton	Power Supplies	Triton 9100/RL2000/RL5000/RT2000 Dual Power Supply Sub-Assembly Repair	\$ 150.00
09110-00176	08010-01511	Triton	Power Supplies	Triton 9100 Single Power Supply Assembly Repair	\$ 150.00
09600-02019	08010-02000	Triton	Power Supplies	Triton 9600 Power Supply Assembly Repair	\$ 150.00
09600-02082	08010-00033	Triton	Power Supplies	Triton 9600 110 Volt Power Supply Assembly (NMD-50 Only) Repair	\$ 225.00
09700-00007	08010-00068	Triton	Power Supplies	Triton 9700 Single Power Supply Assembly	\$ 150.00
09800-02012	08010-03005	Triton	Power Supplies	Triton MAKO Power Supply Assembly Repair	\$ 150.00
09200-00029	08010-01029	Triton	Power Supplies	Triton FT5000XP Single Power Supply Repair	\$ 150.00
09200-00033	08010-01033	Triton	Power Supplies	Triton RL5000XP Single Power Supply Repair	\$ 150.00
09200-00064	08010-00101	Triton	Displays	Triton RL5000 Xscale 10.4" Standard Display Repair	\$ 350.00
09200-00016	08010-00144	Triton	Displays	Triton FT5000 Xscale 10.4" Standard Display Repair	\$ 350.00
09200-00099	08010-00099	Triton	Displays	Triton RL5000 X2 10.4" Standard Display Repair	\$ 350.00
09200-00010	08010-00110	Triton	Displays	Triton FT5000/RL5000 Xscale 10.4" High-Bright Display Repair	\$ 400.00
09200-00091	08010-10091	Triton	Displays	Triton FT5000/RL5000 X2 10.4" High-Bright Display Repair	\$ 400.00
03015-00195	08010-06054	Triton	Displays	Triton FT5000/RT2000 5.7" Rear Service Panel Touchscreen Display Repair	\$ 200.00
01160-00044	08010-10044	Triton	Displays	Triton RL2000 8" Color Display Repair	\$ 250.00
09110-00066		Triton	Displays	Triton FT5000 Monochrome RSP Display Assembly Repair	\$ 150.00
09110-00169	08010-11295	Triton	Displays	Triton FT7000 LCD Color Display Repair	\$ 600.00
09110-00170	08010-11311	Triton	Displays	Triton FT7000 LCD High Bright Color Display Repair	\$ 700.00
03015-00130	08010-00118	Triton	Cabinetry	Triton FT5000/FT5000XP Shutter Assembly Tableless Repair	\$ 75.00
03015-00164	08010-11313	Triton	Cabinetry	Triton FT7000 Shutter Assembly Repair	\$ 100.00
09100-00268	08010-00268	Triton	Dispensers	Triton TDM Mainboard (DC Style Motor) Repair*	\$ 99.00
09100-00116	08010-01501	Triton	Dispensers	Triton TDM Mainboard (Stepper Style Motor) Repair*	\$ 99.00
09100-00139	08010-10139	Triton	Dispensers	Triton TDM-50 Mainboard Repair*	\$ 99.00
09005-00133	08010-11277	Triton	Dispensers	Triton TDM-100 Dispenser w/Cassette Standard Repair	\$ 199.00

09005-00140 08010-11283	Triton	Dispensers	Triton TDM-150 Dispenser w/Cassette Standard Repair	\$ 199.00
09005-00133 08010-11277	Triton	Dispensers	Triton TDM-100 Dispenser w/Cassette Deluxe Repair (Includes Mainboard)	\$ 373.00
09005-00140 08010-11283	Triton	Dispensers	Triton TDM-150 Dispenser w/Cassette Deluxe Repair (Includes Mainboard)	\$ 373.00
09015-00123 08010-11123	Triton	Dispensers	Triton TDM-100 Dispenser w/Cassette & Extension Standard Repair	\$ 249.00
09015-00113 08010-01119	Triton	Dispensers	Triton TDM-150 Dispenser w/Cassette & Extension Standard Repair	\$ 249.00
09015-00123 08010-11123	Triton	Dispensers	Triton TDM-100 Dispenser w/Cassette & Extension Deluxe Repair (Includes Mainboard)	\$ 423.00
09015-00113 08010-01119	Triton	Dispensers	Triton TDM-150 Dispenser w/Cassette & Extension Deluxe Repair (Includes Mainboard)	\$ 423.00
09015-00115 08010-11115	Triton	Dispensers	Triton TDM-200 Dispenser w/Cassette Repair (Includes Mainboard)	\$ 400.00
09015-00116 08010-11116	Triton	Dispensers	Triton TDM 250 Dispenser w/Cassette Repair (Includes Mainboard)	\$ 400.00
09015-00125 08010-11125	Triton	Dispensers	Triton TDM-200 Dispenser w/Cassette & Extension Repair (Includes Mainboard)	\$ 425.00
09015-00120 08010-11120	Triton	Dispensers	Triton TDM-250 Dispenser w/Cassette & Extension Repair (Includes Mainboard)	\$ 425.00
09005-00500 08010-01158	Triton	Dispensers	Triton TDM-50 Dispenser Repair	\$ 249.00
09005-00005 08010-05000	Triton	Dispensers	Triton Mako Dispenser Repair (Includes Mainboard)	\$ 350.00
09005-00312 08010-06038	Triton	Cassettes	Triton TDM Cassette Repair (Long or Short)	\$ 100.00
03016-00100 08010-06043	Triton	Keypads	Triton 8100/9100 VEPP English Keypad Repair**	\$ 150.00
03016-00101 08010-06044	Triton	Keypads	Triton 8100/9100 VEPP French Keypad Repair**	\$ 150.00
03016-00200 08010-06045	Triton	Keypads	Triton 9700 VEPP English Keypad Repair**	\$ 150.00
03016-00201 08010-06046	Triton	Keypads	Triton 9700 VEPP French Keypad Repair**	\$ 150.00
03016-00300 08010-06047	Triton	Keypads	Triton 9600 VEPP English Keypad Repair**	\$ 150.00
03016-00301 08010-06048	Triton	Keypads	Triton 9600 VEPP French Keypad Repair**	\$ 150.00
03016-00002 08010-06049	Triton	Keypads	Triton FT5000/RL5000/RT2000 VEPP English Keypad Repair**	\$ 150.00
03016-00003 08010-06050	Triton	Keypads	Triton FT5000/RL5000/RT2000 VEPP French Keypad Repair**	\$ 150.00
03016-00004 08010-06051	Triton	Keypads	Triton FT5000/RL5000/RT2000 VEPP Dutch Keypad Repair**	\$ 150.00
03016-11102 08010-11102	Triton	Keypads	Triton FT5000XP/RL5000XP/FT7000 Non-Heated Metal Sped Assembly Repair**	\$ 150.00
03016-20120 08010-20120	Triton	Keypads	Triton FT/RL5000 & RL/RT2000 T5 PCI Keypad Assembly Repair**	\$ 400.00
42015-10001	Hantle	Power Supplies	Hantle/Tranax MB1500/2100 Power Supply Repair	\$ 150.00
42015-10006	Hantle	Dispensers	Hantle/Tranax 1k Note CDU Dispenser Repair	\$ 250.00
42015-10012	Hantle	Dispensers	Hantle/Tranax 2k Note CDU Dispenser Repair	\$ 250.00
42015-10037	Hantle	Dispensers	Hantle/Tranax Drawer Type Dispenser Repair	\$ 200.00
42015-10002	Hantle	Dispensers	Hantle/Tranax 1k Note CDU Dispenser Board Repair (Short)	\$ 150.00

42015-10051	Hantle	Dispensers	Hantle/Tranax 1k Note CDU Drawer Type Dispenser Board Repair (Short)	\$ 150.00
42015-10003	Hantle	Dispensers	Hantle/Tranax 2k Note CDU Dispenser Board Repair (Short)	\$ 150.00
42015-10007	Hantle	Cassettes	Hantle/Tranax 1k Note CDU Cassette Repair	\$ 120.00
42015-10013	Hantle	Cassettes	Hantle/Tranax 2k Note CDU Cassette Repair	\$ 120.00
42015-10016	Hantle	Printers	Hantle/Tranax MB1500 Printer Assembly Repair	\$ 150.00
42015-10004	Hantle	Printers	Hantle/Tranax MB1500 Printer Controller Board Repair	\$ 85.00
42015-20005	Hantle	Mainboards & Electronics	Hantle/Tranax MB1000/MB1500 Mainboard Component Repair	\$ 150.00
42015-20014	Hantle	Mainboards & Electronics	Hantle/Tranax MB1500 ARM 9 Mainboard Component Repair	\$ 150.00
42021-20001	Hantle	Mainboards & Electronics	Hantle/Tranax MB2100 Color Mainboard Component Repair	\$ 150.00
41017-10001	Hantle	Mainboards & Electronics	Hantle/Tranax MB1700 Mainboard Component Repair	\$ 150.00
41117-10005	Hantle	Mainboards & Electronics	Hantle/Tranax MB1700w Mainboard Component Repair	\$ 225.00
42015-10001	Nautilus Hyosung	Power Supplies	Nautilus Hyosung MB1500/2100 Power Supply Repair	\$ 150.00
42015-10006	Nautilus Hyosung	Dispensers	Nautilus Hyosung 1k Note CDU Dispenser Repair	\$ 250.00
42015-10012	Nautilus Hyosung	Dispensers	Nautilus Hyosung 2k Note CDU Dispenser Repair	\$ 250.00
42015-10037	Nautilus Hyosung	Dispensers	Nautilus Hyosung MB1500 Drawer Type Dispenser Repair	\$ 200.00
42015-10002	Nautilus Hyosung	Dispensers	Nautilus Hyosung 1k Note CDU Dispenser Board Repair (Short)	\$ 150.00
42015-10051	Nautilus Hyosung	Dispensers	Nautilus Hyosung 1k Note CDU Drawer Type Dispenser Board Repair (Short)	\$ 150.00
42015-10003	Nautilus Hyosung	Dispensers	Nautilus Hyosung 2k Note CDU Dispenser Board Repair (Short)	\$ 150.00
42015-10007	Nautilus Hyosung	Cassettes	Nautilus Hyosung 1k Note CDU Cassette Repair	\$ 120.00
42015-10013	Nautilus Hyosung	Cassettes	Nautilus Hyosung 2k Note CDU Cassette Repair	\$ 120.00
42015-10016	Nautilus Hyosung	Printers	Nautilus Hyosung MB1500 Printer Assembly Repair	\$ 150.00
42015-10004	Nautilus Hyosung	Printers	Nautilus Hyosung MB1500/MB1800/MB1800 CE Printer Controller Board Repair	\$ 85.00
42015-20005	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB1000/MB1500 Mainboard Test & Basic Repair	\$ 100.00
42015-20005	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB1000/MB1500 Mainboard Component Repair	\$ 150.00
42015-10014	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB1500 ARM 9 Mainboard Test & Basic Repair	\$ 100.00

42015-20014	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB1500 ARM 9 Mainboard Component Repair	\$ 150.00
42021-20001	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB2100 Color Mainboard Test & Basic Repair	\$ 100.00
42021-20001	Nautilus Hyosung	Mainboards & Electronics	Nautilus Hyosung MB2100 Color Mainboard Component Repair	\$ 150.00
09005-11327 08010-11327	Talaris	Dispensers	Talaris SDD Front Feed Dispenser Standard Repair	\$ 249.00
09005-11327 08010-11327	Talaris	Dispensers	Talaris SDD Front Feed Dispenser Deluxe Repair (Includes Board)	\$ 415.00
09005-00122 08010-00164	Talaris	Dispensers	Talaris NMD-50 Dispenser Standard Repair*	\$ 400.00
09005-00096 08010-11196	Talaris	Dispensers	Talaris NMD-50 Dispenser (for RL2000) Standard Repair*	\$ 400.00
09005-00122 08010-00164	Talaris	Dispensers	Talaris NMD-50 Dispenser Complete Refurbishment*	\$ 550.00
09005-00096 08010-11196	Talaris	Dispensers	Talaris NMD-50 Dispenser (for RL2000) Complete Refurbishment*	\$ 550.00
09005-00213 08010-00162	Talaris	Dispensers	Talaris NMD-100 180mm Rear Service Dispenser Standard Repair*	\$ 500.00
09005-00215 08010-00163	Talaris	Dispensers	Talaris NMD-100 320mm Rear Service Dispenser Standard Repair*	\$ 500.00
09005-00219 08010-00004	Talaris	Dispensers	Talaris NMD-100 Front Service Dispenser Standard Repair*	\$ 500.00
09005-00213 08010-00162	Talaris	Dispensers	Talaris NMD-100 180mm Rear Service Dispenser Complete Refurbishment*	\$ 650.00
09005-00215 08010-00163	Talaris	Dispensers	Talaris NMD-100 320mm Rear Service Dispenser Complete Refurbishment*	\$ 650.00
09005-00219 08010-00004	Talaris	Dispensers	Talaris NMD-100 Front Service Dispenser Complete Refurbishment*	\$ 650.00
09005-00110 08010-01015	Talaris	Dispensers	Talaris MiniMech Dispenser Repair (Includes Mainboard)	\$ 325.00
08010-02004	Talaris	Dispensers	Talaris SDD Rear Feed Dispenser Deluxe Repair (Includes Board)	\$ 415.00
09005-00508 08010-02005	Talaris	Cassettes	Talaris SDD Cassette Repair	\$ 150.00
09005-02059 08010-02059	Talaris	Cassettes	Talaris NMD-50 Cassette Repair	\$ 150.00
09005-00001 08010-00007	Talaris	Cassettes	Talaris NMD-100 Cassette Repair	\$ 150.00
09005-00000 08010-00008	Talaris	Cassettes	Talaris NMD-100 Reject Cassette Repair	\$ 150.00
08010-00035	Talaris	Dispenser Components	Talaris SDD Main Controller Board*	\$ 99.00
04008-00047	Talaris	Dispenser Components	Talaris MiniMech Mainboard Repair*	\$ 99.00
04005-00001 08010-00015	Talaris	Dispenser Components	Talaris NMD-100 Bundle Output Unit Repair	\$ 100.00
54005-00103 08010-00093	Talaris	Dispenser Components	Talaris NMD-100 Note Diverter Unit Repair	\$ 100.00
04005-00034 08010-00023	Talaris	Dispenser Components	Talaris Note Feeder Controller Board (NFC 100/101) Repair	\$ 150.00
54005-00499 08010-06058	Talaris	Dispenser Components	Talaris Note Feeder Controller Board (NFC 200) Repair	\$ 150.00
54005-00064 08010-00051	Talaris	Dispenser Components	Talaris NMD-100 Stacker Presenter Controller Board (SPC 101) Repair	\$ 200.00

04005-00062 08010-00038	Talaris	Dispenser Components	Talaris NMD-100 Central Machine Controller (CMC 100/101) Repair*	\$ 99.00
04005-00165 08010-11309	Talaris	Dispenser Components	Talaris NMD-50 Central Machine Controller (CMC 50) Repair*	\$ 99.00
54005-00108 08010-00095	Talaris	Dispenser Components	Talaris NMD-100 Central Machine Controller (CMC 200) Repair*	\$ 99.00
54005-00065 08010-00052	Talaris	Dispenser Components	Talaris NMD-100 Bundle Carriage Unit Repair	\$ 300.00
54005-00037 08010-00096	Talaris	Dispenser Components	Talaris NMD-50/100 Extension for One Cassette Repair	\$ 300.00
54005-00060 08010-00017	Talaris	Dispenser Components	Talaris NMD-100 Power Supply Repair	\$ 300.00
04005-00460 08010-00460	Talaris	Dispenser Components	Talaris NMD-50/100 Note Feeder Unit Repair	\$ 350.00
54005-00160 08010-00024	Talaris	Dispenser Components	Talaris NMD-50 Note Transport Unit	\$ 400.00
04005-00461 08010-00461	Talaris	Dispenser Components	Talaris NMD-50/100 Note Qualifier Unit Repair	\$ 420.00
09005-00129 08010-00300	Fujitsu	Dispensers	Fujitsu F510 Dispenser Repair	\$ 600.00
08010-11133	Fujitsu	Dispensers	Fujitsu F100 Dispenser Repair	\$ 400.00
06100-00112 08010-11319	Fujitsu	Cassettes	Fujitsu F510 Cassette Repair	\$ 200.00
37000-20004	LG N-System	Dispensers	LG Dispenser ezCDM 1000 Repair	\$ 150.00

General Policies for Participation in ATMGurus Warranty Program:

- All returns require a Return Merchandise Authorization (RMA) obtained through your Customer Service Guru or by submitting a Repair Order/Warranty Exchange Request online. or contact Customer Service Guru by e-mail at customer.service@atmgurus.com or by telephone at +1-901-728-6487 or 1-888-7-ATMGurus (1-888-728-6487) toll free in North America and they will generate a sales order for your repair, Items received in without an RMA are subject to return without processing of your warranty claim.
- All components must be returned in proper packaging. Damage resulting from improper packaging subject to additional fees or return without processing of your warranty claim.
- Warranty does not include improper use, acts of nature, failures resulting from poor operating environment, or failure to adhere to ATMGurus policies.
- Any items that have been altered or modified outside the specifications set forth by atmgurus may not be accepted as a warranty return. Incomplete components (parts missing) may not be accepted as valid warranty returns. ATMGurus reserves the right in determining acceptance of warranty claim.
- Items returned that are not valid warranty claims (not originally obtained through ATMGurus) will be returned without processing.
- Items returned under warranty must be equivalent to the part(s) that were advanced out as a replacement. In the event they are not, your claim may be denied or you may be invoiced for the difference in value. You will be notified of your option(s) prior to final ruling.

Failure to comply with warranty guidelines can result in probation and exclusion from participating in the program.